

Date	Category Direct / Indirect	Type	Location	Complaint Investigation
6/01/2018	Complaints Line	Noise	Moolarben Road	Investigation revealed no unusual mining operations were occurring at the time. Monitoring results indicated acceptable Noise levels. No actions required.
27/01/2018	Complaints Line	Noise	Ridge Road	Investigation revealed no unusual mining operations were occurring at the time. Monitoring results indicated acceptable Noise levels. No actions required.
27/01/2018	Complaints Line	Noise	Ulan Road	Investigation revealed no unusual mining operations were occurring at the time. Monitoring results indicated acceptable Noise levels. Operational adjustments were made.
27/01/2018	Complaints Line	Noise	Ridge Road	Investigation revealed no unusual mining operations were occurring at the time. Monitoring results indicated acceptable Noise levels. Operational adjustments were made..
28/01/2018	Complaints Line	Noise	Ridge Road	Investigation revealed no unusual mining operations were occurring at the time. Monitoring results indicated acceptable Noise levels. No actions required.
26/02/2018	Complaints Line	Blast	Winchester Crescent	Investigation revealed that no blast was fired by MCO on 26/02/2018.
6/03/2018	Complaints Line	Blast	Winchester Crescent	Investigation revealed a blast was fired at MCO on 06/03/18. Overpressure and vibration results within compliance limits.
7/03/2018	Complaints Line	Blast	Winchester Crescent	Investigation revealed a blast was fired at MCO on 07/03/18. Overpressure and vibration results within compliance limits.
11/03/2018	Complaints Line	Noise	Ridge Road	Investigation revealed no unusual mining operations were occurring at the time. Monitoring results indicated acceptable Noise levels. No actions required.
12/03/2018	Complaints Line	Noise	Ridge Road	Investigation revealed no unusual mining operations were occurring at the time. Monitoring results indicated acceptable Noise levels. No actions required.
19/03/2018	Complaints Line	Other	Ridge Road	No action required.
21/03/2018	Complaints Line	Blast	Winchester Crescent	Investigation revealed a blast was fired at MCO on 06/03/18. Overpressure and vibration results within compliance limits.
27/03/2018	Complaints Line	Noise	Ridge Road	Investigation revealed no unusual mining operations were occurring at the time. Monitoring results indicated acceptable Noise levels. Operational adjustments were made.
1/04/2018	Complaints Line	Noise	Ridge Road	Investigation revealed no unusual mining operations were occurring at the time. Monitoring results indicated acceptable Noise levels. No actions required.
3/04/2018	Complaints Line	Blast	Winchester Crescent	Investigation revealed that no blast was fired by MCO on 03/04/18.
6/04/2018	Complaints Line	Noise	Ridge Road	Investigation revealed no unusual mining operations were occurring at the time. Monitoring results indicated acceptable Noise levels. No actions required.
10/04/2018	Complaints Line	Noise	Ridge Road	Investigation revealed no unusual mining operations were occurring at the time. Monitoring results indicated acceptable Noise levels. Operational adjustments were made.

Date	Category Direct / Indirect	Type	Location	Complaint Investigation
11/04/2018	Complaints Line	Noise	Ridge Road	Investigation revealed no unusual mining operations were occurring at the time. Monitoring results indicated acceptable Noise levels. Operational adjustments were made.
11/04/2018	Complaints Line	Noise	Ridge Road	Investigation revealed no unusual mining operations were occurring at the time. Monitoring results indicated acceptable Noise levels. No actions required.
21/04/2018	Complaints Line	Noise	Ridge Road	Investigation revealed no unusual mining operations were occurring at the time. Monitoring results indicated acceptable Noise levels. Operational adjustments were made.
22/04/2018	Email	Blast	Wyaldra Lane	Investigation revealed a blast was fired at MCO on 21/04/18. Overpressure and vibration results within compliance limits.
25/04/2018	Complaints Line	Noise	Ulan Road	Investigation revealed no unusual mining operations were occurring at the time. Monitoring results indicated acceptable Noise levels. Operational adjustments were made.
6/05/2018	Complaints Line	Noise	Winchester Crescent	Investigation revealed no unusual mining operations were occurring at the time. Monitoring results indicated acceptable noise levels. Operational adjustments were made.
25/05/2018	Complaints Line	Noise	Ulan Road	Investigation revealed no unusual mining operations were occurring at the time. Monitoring results indicated acceptable noise levels.
25/05/2018	Complaints Line	Noise	Winchester Crescent	Investigation revealed no unusual mining operations were occurring at the time. Monitoring results indicated acceptable noise levels.